

RP-36-03'ENCTHECVQP

If you, as a user of IESNA/NALMCO RP-36-03, *Recommended Practice for Planned Indoor Lighting Maintenance*, believe you have located an error not covered by the following revisions, you should e-mail your information to Pat McGillicuddy pmcgillicuddy@ies.org or send a letter to: Pat McGillicuddy, Manager of Technology, IES, 120 Wall Street 17th Floor, New York, NY 10005. Additions will be posted to this list online as they become available. This errata list was last updated on **December 7, 2005**.

Please confine your comments to specific typographical errors or misstatements of fact in the RP-36-03 text and/or graphics. Do not attempt to revise or update the document itself.

Disclaimer Regarding the Application of RP-36-03 to Industrial Spaces

The NALMCO study that was the basis for the calculation of Luminaire Dirt Depreciation (LDD) factors in this Recommended Practice included commercial, educational, and retail spaces — but not industrial spaces. Therefore, Section 2.1.2 and Section 3.0 of this Practice (including all subsections) do not apply to industrial spaces, new or retrofit. The reader is referred to the *IESNA Lighting Handbook*, 9th Edition (Chapter 9, Lighting Calculations), when LDD factors need to be determined for industrial spaces/applications.